HILLSBORO, OR 97124

ACTT: 8827.1 hours / Hobbs: 1250.1 hours

Left engine S/N P-79297, TSN: 4344.4 hours / TSO: 1249.5 hours TOLL FREE 800.448,2376 Right engine S/N P-79001, TSN: 6658.7 hours / TSO: 1249.5 hours

TEL 503.640.3711

Fax 503.681.6513 Performed Annual/150 hour inspection per current Commander Periodic inspection. AD's researched WWW.AEROAIR.COM through 2013-02.



- AD2012-02-06 "First Turbines" is not applicable by first turbine serial number (both engines).
- Commander Service Bulletin 241, Rev 1 "Fuselage Attachment to Wing Main Spar- Inspection and Reinforcement" dated 10/26/2012, Parts 1 and 2. This is terminating action for this SB. Completed form 337 for this modification dated Jan. 31, 2013.
- Garmin Service Bulletin 1225, Rev. A "GNS400/500 Series Software Upgrade"- upgraded both GNS-430's main software to version 5.0 and GPS software to version 5.0 per SB instructions. Replaced POH Supplement with updated Supplement.
- Garmin Service Bulletin 1229, Rev. A "G-600 Primary Flight Display Software Upgrade" upgraded both G-600 PFD displays to software version 6.11, both AHRS's to software level 3.03 and both ADC's to software level 3.09 per SB instructions.

Performed the following scheduled maintenance:

- · Annual engine magnesium housings corrosion inspection.
- · Annual ELT inspection per 14 CFR part 91.207
- ELT battery replaced with a new battery P/N 452-0133, S/N 357247-066 with expiration date of Jan.
- · Annual landing gear control assembly lube.
- · Annual portable fire bottle weight check.
- Annual emergency battery (PS835) capacity check.
- Annual/450 hour emergency exit operational check.
- Annual/450 hour bleed air system leak check.
- Annual / 500 hour Keith air conditioner inspection per STC ICA.
- Annual / 800 hour initial main battery capacity check.
- 150 hour engine P-3 filter cleaning and inspection.
- 450 hour engine fuel nozzles cleaning and flow check. Replaced left engine fuel nozzles with 10 each overhauled nozzles P/N 3103235-9, -11, IAW Honeywell TPE331-10 EMM 73-10-09. Reference 8130-3 issued by Tennessee Aircraft co. FAA CRS# QTFR573L, and dated 12-12-2012. Replaced right engine fuel nozzles with 10 each overhauled nozzles P/N: 3103235-8, -11, IAW Honeywell TPE331-10 EMM 73-10-09. Reference 8130-3 issued by Tennessee Aircraft Co. FAA CRS# QTFR573L, dated: 12-14-2012. Leak check satisfactory.
- · 450 hour hydraulic reservoir filter change.
- 450 hour ACM oil change (BP2380 oil).
- · 950 hour fuel quantity indication system calibration.
- · 950 hour fuel low warning system check.
- 5 year N2 cylinder hydrostatic test. Inspection and hydrostatic testing of N2 cylinder p/n 710031-501, s/n 81566T accomplished by Aerospace Turbine Rotables Inc., FAA CRS# NV2R045L. Reference FAA form 8130-3 issued by that facility and dated Dec 18, 2012.

Note: determined by log review that both engines are post SB 72-0486, therefore tach/gen spline inspections are no longer required.

Performed the following additional maintenance:

- Replaced emergency exit lock tang springs with new springs P/N 330109-67.
- Replaced right side indirect light tube (midway back) with a new lamp tube P/N 5113WW.
- Corrected aircraft not pressurizing by replacing 3-way valve with a new vacuum shutoff valve P/N 717, S/N 2414A.
- Replaced pilots and copilots rudder pedal boots with new boots from Commander Kit No. PK50-2 and PK50-3.
- Replaced flap chafe tape as needed.
- Resealed left aft brake caliper and bled brake.
- Replaced one fastener on left cowl with a new fastener P/N 4002-4S.
- Patched wing deice boots as needed and touched edge sealer where necessary
- Replaced right horizontal stabilizer deice boot with a new Goodrich boot P/N P25S-7D5015-04, S/N
- Replaced right elevator trim tab actuator fairing with a new fairing P/N 440000-719.
- Touched up paint as needed.



Page 2 of 2 (ACTT: 8827.1 hours, Feb. 11, 2013)

- Replaced left main tire with a new tire P/N 850T06-3, S/N 2202380.
- Replaced both nose wheel bearings with new bearings P/N 13889-2629.
- · Repaired center fuel tank vapor box as needed.
- Replaced entry door emergency unlock switch with a new switch P/N TIGL5B1CWHFN.
- · Reinstalled missing copilot's instrument panel post light.
- Repaired right exhaust fairing using riveted aluminum doublers installed per AC43.13-1B, Chapter 4, Section 4.
- Replaced center lower fuel bladder with a new bladder P/N 630204-505, S/N 126.
- · Repaired wiring to correct inoperative instrument panel post lights.
- Replaced two missing fasteners in left wing lower spar cap just outboard of the fuselage.
- Replaced right main gear inboard door support arm with a new support arm P/N 330093-508.
- Replaced left picture window inner pane with a new inner pane P/N 330367-7, S/N 200355.
- Replaced left picture window outer pane with a new outer pane P/N 330367-9, S/N 200381.
- Replaced right picture window inner pane with a new inner pane P/N 330367-8, S/N 200316.
- Repaired broken wire at stall warning box.
- · Repaired coax connector at ELT.
- Replaced ELT connector (airframe side) with a new connector P/N 151-5012.
- Replaced left engine start/generator garloc seal with a new seal P/N 3103872-1.
- Troubleshot intermittent fuel quantity indication system, found and corrected faulty shield ground on Hi-Z
 wire at connector P49A (aft pressure bulkhead). Performed fuel quantity system calibration with no
 defects.

APPROVAL FOR RETURN TO SERVICE

Aero Air LLC certifies that the above airframe/engine has been inspected IAW an Annual / 150 hour inspection and has been determined to be in airworthy condition on the above date per the requirements of 14 CFR Part 91.409 (f)(3). Pertinent details are on file at this agency under the above work order.



Inspector, Aero Air LLC, CRS# O9IR003Y 2050 NE 25th Ave. Hillsboro, OR 800-448-2376

N13622, Commander 690B, S/N 11469

W.O. MPROP4693

Feb. 14, 2013

ACTT: 8827.1 hours/hobbs: 1250.1 hours

Performed the following maintenance:

- Corrected left wing fuel leak by replacing left outboard wing, aft inboard bladder with a new bladder P/N 630064-519, S/N 128. Replaced one clamp on left inboard wing, aft outboard bladder, tightened clamps as needed.
- Replaced landing gear squat switch with a new switch P/N 800237-15.

AEROAIR

APPROVAL FOR RETURN TO SERVICE

Aero Air LLC certifies that the above aircraft has been inspected and repaired per current FAR's and is approved for return to service only for the work performed. Pertinent details are on file at this agency under the above work order.

Signed

Inspector, Aero Air LLC, CRS# O9IR003Y 2050 NE 25th Ave. Hillsboro, OR 800-448-2376

AMERICAN AVIONICS, 7023 PERIMETER RD. SEATTLE, WA 98108

Make/Model: Rockwell 690B

Serial Number: 11469

Tach: 3153.35

Registration Number: N13622

Date: 12 March 2013

Work/Order: A13851

Removed broken ELT antenna and replaced with ARTEX p/n 110-323 s/n 0444

This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under work order number: A13851

Signed

spector (6) CRS# 1AMR980Y

Thomas Kaminski